




DETECTABLE WARNING MAT



200 Truncated Domes



Traction bumps




DETECTABLE WARNING SYSTEMS INC.

DWG :


2X2 INLINE DOME

SCALE: NOT TO SCALE

DATE: 4/1/2002



DETECTABLE WARNING MAT




DETECTABLE WARNING SYSTEMS INC.




DWG : 2X3 INLINE DOME

SCALE: NOT TO SCALE


DATE: 9/15/05




DETECTABLE WARNING MAT




DETECTABLE WARNING SYSTEMS INC.	
DWG : 2X4 INLINE DOME	
SCALE: NOT TO SCALE	DATE: 4/1/2002




DETECTABLE WARNING MAT



250 Truncated Domes



Traction bumps




DETECTABLE WARNING SYSTEMS INC.

DWG : 2 X 5 INLINE DOME

SCALE: NOT TO SCALE


DATE: 4/1/2002



DETECTABLE WARNING MAT

195
Truncated Domes


36.25



30.50


Double Edge

Detail A



Traction bumps

Detail B




DETECTABLE WARNING SYSTEMS INC.

DWG :




3X2-1/2 INLINE DOME

SCALE: NOT TO SCALE

DATE: 4/1/2002



DETECTABLE WARNING MAT




DETECTABLE WARNING SYSTEMS INC.

DWG :




3X4 INLINE DOME

SCALE: NOT TO SCALE

DATE: 4/1/2002



DETECTABLE WARNING MAT



DETECTABLE WARNING SYSTEMS INC.

DWG :

INLINE DOME WEDGE

SCALE: NOT TO SCALE

DATE: 4/1/2002

